



Pictures and repainted images of all sample intersections

Section 1 pictures of most samples are SE images, whereas the rest of the pictures are taken in reflected light with an optical microscope. Empty bubbles appear black, while bubbles filled with epoxy are grey. White bubbles are filled with alumina powder that was used for polishing.


Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1




Section 2




Section 3





Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1




Section 2




Section 3



Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1




Section 2




Section 3




Section 1



Section 2




Section 3




C17_D75


Section 1




Section 2




Section 3




Section 1




Section 2




Section 3



Section 1



Section 2



Section 3

